

Final Reclamation and Stormwater Inspection

December 12, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 321357

Inspection Document #: 674902329

Weld County, CO

SWSW Section 18 T1N R66W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: KERR MCGEE OIL & GAS ONSHORE LP – 47120/1N66W18
Location ID: 418977



Photo 1. Photo taken from the well location looking towards the facility, facing East. Appears the Operator has not built the wells RIVERBEND #12-18 and #13-18 on the active location.