

Inspection Photos

Location Name: PHILADELPHIA CREEK 25

Location ID: 05-103-08366

Inspection: 679702255



Photo 1. Location looking east.



Photo 2. Tank without label for NFPA, capacity, and contents.



Inspection Photos
Location Name: PHILADELPHIA CREEK 25
Location ID: 05-103-08366
Inspection: 679702255



Photo 3. Barrel stored on location without secondary containment.



Photo 4. Storm water channel through berm next to tank.

Inspection Photos

Location Name: PHILADELPHIA CREEK 25

Location ID: 05-103-08366

Inspection: 679702255



Photo 5. Riser next to well head not capped or locked out tagged out

