

N.PARACHUTE EF06C-32-L29

API# 05-045-11635

Inspection # 689702262



The phone number for local emergency services (911 where available) and the public road used to access the site is not posted on battery sign.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

N.PARACHUTE EF06C-32-L29

API# 05-045-11635

Inspection # 689702262



Entrance location sign.

N.PARACHUTE EF06C-32-L29

API# 05-045-11635

Inspection # 689702262



Produced water tank.

N.PARACHUTE EF06C-32-L29

API# 05-045-11635

Inspection # 689702262



Location photo.