

# Inspection Photos

12/12/2018

Operator: DAVIS OIL COMPANY - 22900

Location ID: 381816

Inspection Doc. Number: 682504277

Elbert County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** Photo taken from the south end of the well location, facing northeast. Photo shows well location (foreground) and the former pit (background) remains predominantly bare and exposed soil. Sundry doc. #1494774 indicates additional reclamation work was conducted in 2005, including reseeding.



**Photo 2:** Photo taken from the south end of the well location, facing northwest. Photo shows well location remains predominantly bare and exposed soil.



**Photo 3:** Photo taken from the southwest corner of the former pit, facing north. Photo shows that the pit remains predominantly bare and exposed soil.



**Photo 4:** Photo taken from the southwest corner of the former pit, facing east. Photo shows that the pit remains predominantly bare and exposed soil.



**Photo 5:** Photo taken from the former pit. Photo shows pit remains predominantly bare and exposed soil.



**Photo 6:** Photo taken from the adjacent reference area. Photo shows vegetation in the reference area appears to be predominantly a Blue grama and Buffalo grass community. Very little exposed soils were observed in the reference; well location and pit is not reflective of the reference area.