

# Inspection Photos

12/19/2018

Operator: WESCO OPERATING INC - 95520

Location ID: 317082

Inspection Doc. Number: 682504295

Washington County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** Photo taken from the access road, south of the location facing north. Photo shows that the access road within the crop field remains evident. Insufficient reclamation activities have been conducted in accordance with 1000 series rules. Photo also shows utility power lines (4 poles) leading north from the Rudnik 33-27 ending at the Rudnik 32-27. This is This is surface equipment associated with the abandoned oil and gas location and requires removal.

Inspection Photos  
Operator: WESCO OPERATING INC - 95520  
Location ID: 317082



**Photo 2:** Photo taken from the access road, south of the location facing north. See comments under photo 1

Inspection Photos  
Operator: WESCO OPERATING INC - 95520  
Location ID: 317082



**Photo 3:** Photo taken from well location. Photo shows that crop vegetation has failed to establish over the well.



**Photo 4:** Photo taken from the well location, facing south. Photo shows utility power lines (4 poles) leading north from the Rudnik 33-27 ending at the Rudnik 32-27. This is surface equipment associated with the abandoned oil and gas location and requires removal.



**Photo 5:** Photo taken from the west of the well location, facing east. Photo shows utility power lines remaining. Poles appear to be interfering with the surface owner's agricultural activities.