

**Inspection Photo (s)**  
**KRK 6-10D**  
**API # 05-045-09085**  
**Inspection # 689302714**



**Location Photo #1**



**Location Photo #2, Holes in containment liner.**

**Inspection Photo (s)**  
**KRK 6-10D**  
**API # 05-045-09085**  
**Inspection # 689302714**



**Location Photo #3, Holes in containment liner.**



**Location Photo #4, Holes in containment liner.**



**Inspection Photo (s)**  
**KRK 6-10D**  
**API # 05-045-09085**  
**Inspection # 689302714**



**Location Photo #5, Holes in containment liner.**