

Location Name: Impetro Resources LLC – Reed Tank Battery (317258)
Inspection Date: 12/03/2018



Photo # - 1

Location Name: Impetro Resources LLC – Reed Tank Battery (317258)
Inspection Date: 12/03/2018



Photo # - 2

Separator view northeast



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Impetro Resources LLC – Reed Tank Battery (317258)
Inspection Date: 12/03/2018



Photo # - 3

Skim tank view west, note burrows and erosion in berms



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Impetro Resources LLC – Reed Tank Battery (317258)
Inspection Date: 12/03/2018



Photo # - 4

View from east side of the skim tank across production pit



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Impetro Resources LLC – Reed Tank Battery (317258)
Inspection Date: 12/03/2018



Photo # - 5

View east along the south side of the production pit berm, note dredged pit soil encroaching on crop area



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Impetro Resources LLC – Reed Tank Battery (317258)
Inspection Date: 12/03/2018



Photo # - 6

Southeast corner of the production pit berm, note dredged pit soil encroaching on crop area



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Impetro Resources LLC – Reed Tank Battery (317258)
Inspection Date: 12/03/2018



Photo # - 7

Southeast corner of the production pit berm, note dredged pit soil encroaching on crop area



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Impetro Resources LLC – Reed Tank Battery (317258)
Inspection Date: 12/03/2018



Photo # - 8

View north along the eastern production pit berm, note dredged pit soil encroaching on crop area



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Impetro Resources LLC – Reed Tank Battery (317258)
Inspection Date: 12/03/2018



Photo # - 9

View west along the southern production pit berm, note dredged pit soil encroaching on crop area



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources