

Inspection Photos
Location Name: Richardson G #2 Spill/Release
Spill/Release Point ID #459307



Spill/Release Point ID #459307 location photo.



Excavation along east side of access road.

Inspection Photos
Location Name: Richardson G #2 Spill/Release
Spill/Release Point ID #459307



Excavation along west side of access road.



View towards the west of the work area along the eastern side of the access road.

Inspection Photos
Location Name: Richardson G #2 Spill/Release
Spill/Release Point ID #459307



12" steel casing sleeve under access road.



View to the east along pipeline alignment.

Inspection Photos
Location Name: Richardson G #2 Spill/Release
Spill/Release Point ID #459307



View to the west along pipeline alignment.



3" fiberglass pipelines along east side of access road.

Inspection Photos
Location Name: Richardson G #2 Spill/Release
Spill/Release Point ID #459307



Excavated material along east side of access road. Install BMPs to prevent migration of impacted material.



Impacted material excavated from east side of access road. Install BMPs to prevent migration of impacted material.