

Inspection Photos

12/24/2018

Operator: FOUNDATION ENERGY
MANAGEMENT LLC - 10112

Location ID: 331849

Inspection Doc. Number: 682504337
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the access road entrance, facing east. Photo shows that access road and cattle guard have not been reclaimed.



Photo 2: Photo taken from the southwest end of location, facing northeast. Photo shows location and access road remain predominantly bare and exposed soil. Unable to find evidence that reclamation activities have been conducted.



Photo 3: Photo taken from the southeast end of location, facing northwest. Photo shows location and access road remain predominantly bare and exposed soil. Unable to find evidence that reclamation activities have been conducted.



Photo 4: Photo taken from the northeast end of the location, facing southwest. Photo shows the turn-around portion of the access road. Photo shows no additional reclamation appears to have been conducted. Vegetation observed in photo is predominantly undesirable weedy plant species.




Photo 5: Continued from photo 4. Photo shows location/access road remains predominantly bare and exposed soil, or vegetated by undesirable weedy plant species.



Photo 6: Photo taken from the adjacent reference area. Photo shows reference vegetation. Vegetation observed included Purple threeawn, Sand dropseed, Blue Grama Western wheat.