

Inspection

December 21, 2018

Operator: PINTAIL PETROLEUM LTD – 70430

Location ID: 321567

Inspection Document #: 674902350

Cheyenne County, CO

SWSW Section 23 T15S R46W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: KERR MCGEE OIL & GAS ONSHORE LP – 47120/1N66W18

Location ID: 321567



Photo 1. Photo taken from the access road looking into the tank battery location. Potential spill was observed.