

Inspection Photos

12/24/2018

Operator: MALLARD EXPLORATION LLC - 10670

Location ID: 454592

Inspection Doc. Number: 682504345

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the northeast corner of the location, facing south. Photos 1-3 provide an overview of the location from south, southwest to west. Photo shows only two wells have been drilled on location and are producing. Photo also shows areas of the location that do not appear to be reasonably needed for production.

Inspection Photos
Operator: MALLARD EXPLORATION LLC - 10670
Location ID: 454592



Photo 2: See comments under photo 1.

Inspection Photos
Operator: MALLARD EXPLORATION LLC - 10670
Location ID: 454592



Photo 3: See comments under photo 1.



Photo 4: Photo taken from the west of the location, facing south. Photos 4-6 provide an overview of the location from northeast, southeast to south. Photo shows only two wells have been drilled on location and are producing. Photo also shows areas of the location that do not appear to be reasonably needed for production.

Inspection Photos
Operator: MALLARD EXPLORATION LLC - 10670
Location ID: 454592



Photo 5: See comments under photo 4.



Photo 6: See comments under photo 4.