

Inspection Photos

Operator: Logos Operating

API: 05-067-05591

Date: 12/18/2018



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward.



Photo 3. View of debris within the eastern portion of the project area that needs to be removed.



Photo 4. View of the southern project area from the southeastern corner facing westward. Debris needs to be removed.



Photo 5. View of the western portion of the project area from the northwestern corner facing southward.