

Inspection Photo (s)
Couey 17-3
API # 05-045-07355
Inspection # 689302764



Location Photo #1



**Location Photo #2, Hole in secondary
containment liner.**

Inspection Photo (s)
Couey 17-3
API # 05-045-07355
Inspection # 689302764



**Location Photo #3, Hole in secondary
containment liner.**