

**Inspection Photo (s)**  
**KRK 7-3**  
**API # 05-045-06999**  
**Inspection # 689302772**



**Location Photo #1**

**Location Photo #2**

**Inspection Photo (s)**  
**KRK 7-3**  
**API # 05-045-06999**  
**Inspection # 689302772**



**Location Photo #3, Unmarked, unused flow lines in battery containment.**

**Location Photo #4, Unmarked, unused flow lines in battery containment**