

Inspection Photo (s)
BJM 31-14
API # 05-045-07574
Inspection # 689302775



Location Photo #1



Location Photo #2



Inspection Photo (s)
BJM 31-14
API # 05-045-07574
Inspection # 689302775



**Location Photo #3, Holes in secondary
containment liner.**