

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

12/26/2018

Submitted Date:

12/26/2018

Document Number:

689702292**FIELD INSPECTION FORM**

Loc ID 334365	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: <u>10456</u> Name of Operator: <u>CAERUS PICEANCE LLC</u> Address: <u>1001 17TH STREET #1600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				<b>Findings:</b> 16 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only
Kellerby, Shaun		shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293862	WELL	SI	08/01/2018	GW	045-15145	PARACHUTE RANCH FED. 35-41B	PR
293863	WELL	PR	09/01/2014	GW	045-15146	PARACHUTE RANCH FED 35-42B	PR
293865	WELL	SI	08/01/2018	GW	045-15148	PARACHUTE RANCH FED. 35-41D	PR
293866	WELL	SI	09/01/2018	GW	045-15149	PARACHUTE RANCH FED 35-42A	PR
293867	WELL	PR	01/24/2010	GW	045-15150	PARACHUTE RANCH FED. 35-31D	PR
293868	WELL	SI	10/01/2017	GW	045-15151	PARACHUTE RANCH FED. 35-32C	PR
293869	WELL	SI	05/01/2018	GW	045-15152	PARACHUTE RANCH FED. 35-32B	PR
293870	WELL	PR	01/01/2010	GW	045-15153	PARACHUTE RANCH FED. 35-32A	PR
293871	WELL	PR	11/16/2009	GW	045-15154	PARACHUTE RANCH FED. 35-41C	PR
294767	WELL	PR	01/25/2010	GW	045-15591	PARACHUTE RANCH FED. 35-31B	PR
294768	WELL	PR	11/21/2009	GW	045-15592	PARACHUTE RANCH FED. 35-31A	PR
294769	WELL	PR	12/01/2009	GW	045-15593	PARACHUTE RANCH FED. 35-41A	PR

**General Comment:**

Routine FIU General Field Inspection

**Location**

<b>Lease Road:</b>			
Type	Main		
comment:			
Corrective Action	L	Date:	
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:	866-580-9382	
Corrective Action:		Date: _____

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Unused 500 bbl heated tank on east perimeter of location near separators.		
Corrective Action:	Comply with Rule 603.f .	Date:	03/29/2019

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Type	TANK BATTERY			
Comment:				
Corrective Action:			Date:	
Type	SEPARATOR			
Comment:				
Corrective Action:			Date:	

**Equipment:**

			corrective date
Type: Plunger Lift	# 12		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 13		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	6	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				

**Venting:**

Yes/No		
Comment:		
Corrective Action:		
	Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		
	Date:	

Inspected Facilities									
Facility ID:	293862	Type:	WELL	API Number:	045-15145	Status:	SI	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	293863	Type:	WELL	API Number:	045-15146	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	293865	Type:	WELL	API Number:	045-15148	Status:	SI	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	293866	Type:	WELL	API Number:	045-15149	Status:	SI	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	293867	Type:	WELL	API Number:	045-15150	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	293868	Type:	WELL	API Number:	045-15151	Status:	SI	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	293869	Type:	WELL	API Number:	045-15152	Status:	SI	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	293870	Type:	WELL	API Number:	045-15153	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	293871	Type:	WELL	API Number:	045-15154	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	294767	Type:	WELL	API Number:	045-15591	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	294768	Type:	WELL	API Number:	045-15592	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	294769	Type:	WELL	API Number:	045-15593	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			
Berms	Pass					
Ditches	Pass					
		Ditches	Pass			
Compaction	Pass					
				Material Handling And Spill Prevention	Pass	
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689702293	Inspection 689702292 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4687585">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4687585</a>