

Inspection Photos

12/26/2018

Operator: ST CROIX OPERATING INC # 81490

Location ID: 455607

Inspection Doc. Number: 682504349

Washington County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: ST CROIX OPERATING INC # 81490
Location ID: 455607



Photo 1: Photo taken from the northeast corner of the location, facing south. Photo shows a sotrmwater ditch has been constructed along the perimeter of the pad.



Photo 2: Photo taken from the northeast corner of the location, facing west. Photo shows a sotrmwater ditch has been constructed along the perimeter of the pad.



Photo 3: Photo taken from the northwest corner of the location, facing east. Photo shows a sotrmwater ditch has been constructed along the perimeter of the pad.



Photo 4: Photo taken from the northwest corner of the location, facing south. Photo shows a sotrmwater ditch has been constructed along the perimeter of the pad.



12.26.2018

Photo 5: Photo taken from the southwest corner of the location, facing north. Photo shows a sotrmwater ditch has been constructed along the perimeter of the pad.



Photo 6: Photo taken from the southwest corner of the location, facing east. Photo shows a sotrmwater ditch has been constructed along the perimeter of the pad.



Photo 7: Photo taken from the southeast corner of the location, facing west. Photo shows a sotrmwater ditch has been constructed along the perimeter of the pad.



Photo 8: Photo taken from the southeast corner of the location, facing north. Photo shows a sotrmwater ditch has been constructed along the perimeter of the pad.