

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 454517 Type: WELL API Number: 123-46589 Status: DG Insp. Status: DG

Well Stimulation

Stimulation Company: Liberty Oilfield Services Stimulation Type: HYDRAULIC FRAC

Other: _____

Observation:

Maximum Casing Recorded: _____ PSI

Tubing: _____

Surface: _____

Intermediate: _____

Production: _____

Instantaneous Shut-In Pressure (ISIP) _____

Bradenhead Psi: _____

Frac Flow Back: _____

Fluid: _____

Gas: _____

Comment: Frac crew was on Christmas break at time of inspection.

Corrective Action: _____

Date: _____

BradenHead

Comment: Plumbed to surface

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Ditches	Pass	Gravel	Pass	Covering Materials	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Frac crew was on Christmas break at time of inspection. Gate gaurd and 2 Liberty employee's for fire watch were on site.	silverr	12/28/2018