

Inspection Photos
Location Name: Pathfinder C 14-01 1
Location ID: 429883



PHOTO 1: WELLHEAD



PHOTO 2: WELL SIGN

Inspection Photos
Location Name: Pathfinder C 14-01 1
Location ID: 429883



PHOTO 3: LEVELED AREA WHERE DRILLING RIG SAT LOOKING FROM WELLHEAD TOWARD TOP SOIL PILE



PHOTO 4: CUTTING TANK AND PILE OF MUD SET TO BE HAULED TO DISPOSAL

Inspection Photos
Location Name: Pathfinder C 14-01 1
Location ID: 429883



PHOTO 5: BMP AROUND PILE OF MUD



PHOTO 6: TOP SOIL PILE

Inspection Photos
Location Name: Pathfinder C 14-01 1
Location ID: 429883



**PHOTO 7: BMP'S REMOVED WHEN GATHERING TOP SOIL
WHERE NOT REPLACED AROUND TOP SOIL PILE**



PHOTO 8: ANOTHER LOOK AT LEVELED AREA FOR RIG

Inspection Photos
Location Name: Pathfinder C 14-01 1
Location ID: 429883



PHOTO 9: STAINED SOIL WHERE FUEL TANK WAS DURING DRILLING OPERATIONS



PHOTO 10: STAINED SOIL WHERE FUEL TANK WAS DURING DRILLING OPERATIONS