

**NOLTE 44B-14**  
**API# 05-045-22297**  
**Inspection # 689702324**



**NOLTE 44B-14**  
**API# 05-045-22297**  
**Inspection # 689702324**



**Weeds have been cleared from perimeter.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**NOLTE 44B-14**  
**API# 05-045-22297**  
**Inspection # 689702324**



**Weeds have been cleared from behind separators.**

**NOLTE 44B-14**  
**API# 05-045-22297**  
**Inspection # 689702324**



**Tank has been labeled.**



**NOLTE 44B-14**  
**API# 05-045-22297**  
**Inspection # 689702324**



**Labels are still in disrepair.**