

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/31/2018

Submitted Date:

12/31/2018

Document Number:

689702324**FIELD INSPECTION FORM**

Loc ID 435806	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>10456</u> Name of Operator: <u>CAERUS PICEANCE LLC</u> Address: <u>1001 17TH STREET #1600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				Findings: 21 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435798	WELL	PR	03/20/2014	GW	045-22297	NOLTE 44B-14	PR
435799	WELL	PR	07/09/2014	GW	045-22298	NOLTE 13B-13	PR
435800	WELL	PR	03/11/2014	GW	045-22299	NOLTE 11B-24	PR
435801	WELL	PR	04/08/2014	GW	045-22300	NOLTE 14C-13	PR
435802	WELL	PR	07/18/2014	GW	045-22301	NOLTE 44A-14	PR
435803	WELL	PR	06/29/2014	GW	045-22302	NOLTE 43C-14	PR
435804	WELL	PR	03/23/2014	GW	045-22303	NOLTE 11A-24	PR
435805	WELL	PR	09/17/2014	GW	045-22304	NOLTE 14D-13	PR
435807	WELL	PR	07/21/2014	GW	045-22305	NOLTE 13D-13	PR
435808	WELL	PR	03/15/2014	GW	045-22306	NOLTE 44C-14	PR
435809	WELL	PR	05/08/2014	GW	045-22307	NOLTE 13C-13	PR
435810	WELL	PR	07/05/2014	GW	045-22308	NOLTE 13A-13	PR
435811	WELL	PR	07/12/2014	GW	045-22309	NOLTE 43B-14	PR
435812	WELL	PR	04/24/2014	GW	045-22310	NOLTE 14A-13	PR
435813	WELL	PR	04/12/2014	GW	045-22311	NOLTE 14B-13	PR
435814	WELL	PR	07/11/2014	GW	045-22312	NOLTE 43A-14	PR
435989	WELL	PR	03/04/2014	GW	045-22325	NOLTE 11C-24	PR

General Comment:

Follow up to 11/05/2018 inspection #689702017

LocationOverall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	3 tanks in battery have labels in disrepair. Production tank labels have not been repaired. Rock drill oil tank has been labeled.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	01/06/2019

Emergency Contact Number:

Comment:

Corrective Action: Date:

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds have been addressed.		
Corrective Action:		Date:	

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	435798	Type:	WELL	API Number:	045-22297	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	435799	Type:	WELL	API Number:	045-22298	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	435800	Type:	WELL	API Number:	045-22299	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	435801	Type:	WELL	API Number:	045-22300	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	435802	Type:	WELL	API Number:	045-22301	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	435803	Type:	WELL	API Number:	045-22302	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	435804	Type:	WELL	API Number:	045-22303	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	435805	Type:	WELL	API Number:	045-22304	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	435807	Type:	WELL	API Number:	045-22305	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	435808	Type:	WELL	API Number:	045-22306	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	435809	Type:	WELL	API Number:	045-22307	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	435810	Type:	WELL	API Number:	045-22308	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	435811	Type:	WELL	API Number:	045-22309	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	435812	Type:	WELL	API Number:	045-22310	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	435813	Type:	WELL	API Number:	045-22311	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	435814	Type:	WELL	API Number:	045-22312	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	435989	Type:	WELL	API Number:	045-22325	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well			
Comment:	Producing well		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
Compaction						
Berms						
Ditches						
Check Dams						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689702325	Inspection 689702324 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4691127