

Final Reclamation and Stormwater Inspection

December 28, 2018

Operator: NOBLE ENERGY INC – 100322

Location ID: 332003

Inspection Document #: 674902376

Weld County, CO

NWSE Section 20 T3N R64W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N64W20

Location ID: 332003



Photo 1. Photo taken from the access road, facing Northwest. Appears the Operator has not performed final reclamation activities. The equipment has been removed but the gravel still remains on the access road and location.



Photo 2. Photo taken from the access road facing Southeast. See comments from Photo 1.

Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N64W20

Location ID: 332003



Photo 3. Photo taken from the location, facing Northwest. See comments from Photo 1.



Photo 4. Photo taken from the location, facing West. See comments from Photo 1.