

Inspection Photos
Location Name: MEAGHER 3-1H
Location ID: 05-103-11910
Inspection: 679702444



Photo 1. Location looking southwest.



Photo 2. Tank on right without signage.

Inspection Photos
Location Name: MEAGHER 3-1H
Location ID: 05-103-11910
Inspection: 679702444



Photo 3. Riser not capped or LOTO.



Photo 4. Barrels that appear unused stored in berm area.

Inspection Photos

Location Name: MEAGHER 3-1H

Location ID: 05-103-11910

Inspection: 679702444



Photo 5. Water tank that appears unused.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources