

Inspection Photos

Location Name: WEAVER RIDGE 14-15H

Location ID: 05-103-11932

Inspection: 679702446



Photo 1. Location looking west.



Photo 2. Pump jack 14-15H and tank battery.



Inspection Photos
Location Name: WEAVER RIDGE 14-15H
Location ID: 05-103-11932
Inspection: 679702446



Photo 3. Tank battery.



Photo 4. Gas meter building and separator.

Inspection Photos
Location Name: WEAVER RIDGE 14-15H
Location ID: 05-103-11932
Inspection: 679702446



Photo 5. Well 14-15H2 and emission control device



Photo 6. Tank missing capacity volume.