

N. PARACHUTE EF08B C27A 595

API# 05-045-11570

Inspection # 689702346




No emergency services number or (911) on battery sign.

**N. PARACHUTE EF08B C27A 595**

**API# 05-045-11570**

**Inspection # 689702346**



**Obstructed visibility of battery sign.**



**N. PARACHUTE EF08B C27A 595**

**API# 05-045-11570**

**Inspection # 689702346**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources