

# Inspection Photos

1/03/2019

Operator: GRAND MESA OPERATING CO - 35080

Location ID: 460311

Inspection Doc. Number: 682504361

Lincoln County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** Photo taken from the southeast end of the location, facing west. Photo shows operator has installed surface roughening as a temporary stormwater BMP along perimeter prior to construction activities.



**Photo 2:** Photo taken from the southeast end of the location, facing north. Photo shows operator has installed surface roughening as a temporary stormwater BMP along perimeter prior to construction activities.



**Photo 3:** Photo taken from the north end of the location, facing west. Photo shows operator has installed surface roughening as a temporary stormwater BMP along perimeter prior to construction activities. Photo also shows topsoil salvage in process.

Inspection Photos  
Operator: GRAND MESA OPERATING CO - 35080  
Location ID: 460311



**Photo 4:** Photo taken from the location, facing southeast. Photo shows topsoil salvage in process.