

Inspection Photos

Location Name: WEAVER RIDGE 23-10, 23-7H, 23-7H2

Location ID: 05-103-10679, 11933, 12328

Inspection: 679702459



Photo 1. Location looking north.



Photo 2. Separators and gas meter buildings.



Inspection Photos

Location Name: WEAVER RIDGE 23-10, 23-7H, 23-7H2

Location ID: 05-103-10679, 11933, 12328

Inspection: 679702459



Photo 3. Tank battery.



Photo 4. Emission control device.



Inspection Photos

Location Name: WEAVER RIDGE 23-10, 23-7H, 23-7H2

Location ID: 05-103-10679, 11933, 12328

Inspection: 679702459



Photo 5. Well heads.



Photo 6. Separator valve leaking fluid on ground.

Inspection Photos

Location Name: WEAVER RIDGE 23-10, 23-7H, 23-7H2

Location ID: 05-103-10679, 11933, 12328

Inspection: 679702459



Photo 7. Tanks missing 400 bbl capacity on label.

Photo 8. Pump jack container without label.

Inspection Photos

Location Name: WEAVER RIDGE 23-10, 23-7H, 23-7H2

Location ID: 05-103-10679, 11933, 12328

Inspection: 679702459



Photo 9. Well head without sign. Weaver Ridge 23-7H2.

