

Inspection Photos

Location Name: WEAVER RIDGE 27-1

Location ID: 05-103-10671

Inspection: 679702494



Photo 1. Location looking west.



Photo 2. Gas meter building and separator.



Inspection Photos

Location Name: WEAVER RIDGE 27-1

Location ID: 05-103-10671

Inspection: 679702494



Photo 3. Tank battery.



Photo 4. Pump jack.



Inspection Photos

Location Name: WEAVER RIDGE 27-1

Location ID: 05-103-10671

Inspection: 679702494



Photo 5. Unlabeled container.



Photo 6. Unused container.



Inspection Photos
Location Name: WEAVER RIDGE 27-1
Location ID: 05-103-10671
Inspection: 679702494



Photo 5. Missing tank volume capacity of 300 on label.

