

# Inspection Photos

Operator: BP America

API: 05-067-08360

Date: 12/21/2018



**Photo 1. View of the project area from the northwestern corner facing center.**



**Photo 2. View the northern project area from the northwestern corner facing eastward.**



**Photo 3. View of the western project area from the northwestern project area facing southward.**