

Inspection Photos
Location Name: Ambush 34-22
Location ID: 320345



Photo 1 WH



Photo 2 TNK BTRY

Inspection Photos
Location Name: Ambush 34-22
Location ID: 320345



Photo 3 Stained soil around PU motor



Photo 4 Stained soil load out Crude oil tank

Inspection Photos
Location Name: Ambush 34-22
Location ID: 320345



Photo 5 Bird netting in disrepair



Photo 6 55 gal drum