

Inspection Photos
Location Name: Ambush 24-22
Location ID: 320630



Photo 1 WH



Photo 2 unused equipment, stained soil, trash

Inspection Photos
Location Name: Ambush 24-22
Location ID: 320630



Photo 3 Stained soil and trash



Photo 4 Stained soil and trash

Inspection Photos
Location Name: Ambush 24-22
Location ID: 320630



Photo 5 weeds cut on location