

Inspection Photos
Location Name: POINTER 43-25
Location ID: 413766



PHOTO 1: WELLHEAD



PHOTO 2: WELL SIGN/METER HOUSE

Inspection Photos
Location Name: POINTER 43-25
Location ID: 413766



PHOTO 3: LINER TORE AND BREAKING APART



PHOTO 4: LINER TORE AND BREAKING APART

Inspection Photos
Location Name: POINTER 43-25
Location ID: 413766



PHOTO 5: STAINED SOIL BENEATH DRIVEHEAD HYDRAULIC LINES