

Inspection Photo (s)
Savage 5-23A
API # 05-045-14795
Inspection # 689302920



Location Photo #1



Location Photo #2



Inspection Photo (s)
Savage 5-23A
API # 05-045-14795
Inspection # 689302920



**Location Photo #3, unused flow line riser,
south end of battery.**



**Location Photo #4, non legible chemical unit
label.**

Inspection Photo (s)
Savage 5-23A
API # 05-045-14795
Inspection # 689302920



Location Photo #5, non legible chemical unit label.