

Inspection Photos

1/10/2019

Operator: PCR OPERATING LLC - 10657

Location ID: 313755

Inspection Doc. Number: 682504400

Morgan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the west end of the location, facing east. Photo shows well location remains predominantly bare and exposed soil, or composed of undesirable weedy plant species. Unable to find evidence that reclamation work has been conducted.



Photo 2: Photo taken from the location, facing east. See comments under photo 1



Photo 3: Photo taken from the north end of the location, facing south. See comments under photo 1.



Photo 4: Photo taken from the well location. Photo shows well location remains predominantly bare and exposed soil or undesirable weedy plant species. Vegetation observed within photo Russian thistle.



Photo 5: Photo taken from the west end of the location, facing south. Photo shows access road remains evident and predominantly bare and exposed soil or composed of undesirable weedy plant species.



Photo 6: Photo taken from the access road, facing north. Photo shows access road (blue line) has not been recontoured/regraded to that of the adjacent reference area (yellow line)



Photo 7: Photo taken from the adjacent reference area. Photo shows vegetation over reference. Vegetation observed predominantly Sand dropseed, blue grama, western wheatgrass, sand sage, etc...



Photo 8: Photo taken from the adjacent reference area. Photo shows vegetation over reference. See comments under photo 7.