

MARALEX RESOURCES, INC

Api # 05-077-08613

Inspection # 675001726



photo from west side of location

MARALEX RESOURCES, INC

Api # 05-077-08613

Inspection # 675001726



Photo of tank battery sign at meter run on location

MARALEX RESOURCES, INC

Api # 05-077-08613

Inspection # 675001726



No Well headsigns in place

MARALEX RESOURCES, INC

Api # 05-077-08613

Inspection # 675001726



Photo of tank on location



Tank label containing inaccurate information