

Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Aug 22, 2018 2:13:28 PM MDT
Server Receive Date:	Aug 22, 2018 2:13:41 PM MDT
Reference Number:	20180822-1885802567
Location:	101 S Skylane Dr, Durango, CO 81303, USA
	Aug 22, 2018 2:12:42 PM MDT [View Map]

Information

Name	reclamationtablet
Date	Aug 20, 2018
Well Name	PAN AMERICAN FEE GAS UNIT B 1
API Number	50670579600
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Other Install Wattles Clean Up Weed Debris

Picture North to South



Picture South to North



Picture East to West



Completed work description

Installed erosion logs, treated weeds and removed debris and trash