

Inspection Photos
Location Name: Hill Ranch 10-15V
Location ID: 307916



Photo 1 SEP



Photo 2 WH\ motor skid

Inspection Photos
Location Name: Hill Ranch 10-15V
Location ID: 307916



Photo 3 Unmarked and unused riser no LOTO

Photo 4 Unmarked and unused riser no LOTO