

Inspection Photos
Location Name: HE Cluster Produced Water Tank
Spill/Release Point ID #460636



Spill/Release Point ID #460636 location photo.



HE Cluster Produced Water Tank where release occurred.

Inspection Photos
Location Name: HE Cluster Produced Water Tank
Spill/Release Point ID #460636



Valve configuration changed to prevent reoccurrence.



Earthen containment berm around Tank T-501.

Inspection Photos
Location Name: HE Cluster Produced Water Tank
Spill/Release Point ID #460636



Containment area was mostly snow covered during this inspection.



Soil samples being collected from impacted area.