

Inspection Photos
Location Name: Feit-66N65W /24SWSW
Location #: 322805



Photo #1

Feit 2-24EG (API # 05-123-12084) wellsite

Temporarily Abandoned | TA

No Orange TA/SI tag per agreement



Photo #2

Feit 2-24EG Battery

Shut-In



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Feit-66N65W /24SWSW

Location #: 322805



Photo #3

Feit 2-24EG Crude oil tank

NFPA placard is peeling & NOT legible.

from prev. FIR



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Feit-66N65W /24SWSW

Location #: 322805



Photo #4

Feit 2-24EG Crude oil tank

NFPA placard is peeling & NOT legible.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources