

Inspection Photos

Location Name: MCKENNEY-66N64W /14NWNE

Location #: 305974



Photo #1

McKenney 14-12 (05-123-23763) wellsite

Temporarily Abandoned – TA | LOTO

Unused Equipment removed

No Orange TA/SI tag per agreement



Photo #2

McKenney 14-11, 14-12 Battery

Shut-Down

photo from prev. FIR

