

## Inspection Photos

Location Name: C&K 1-6

Location ID: 05-103-07880

Inspection: 679702690



**Photo 1. Location looking northeast.**



**Photo 2. Well head leaking gas.**



## Inspection Photos

Location Name: C&K 1-6

Location ID: 05-103-07880

Inspection: 679702690



**Photo 3. Tank missing NFPA label. Operator displayed as "31 Operating".**