

Inspection Photos

Location Name: CONTINENTAL 2-17

Location ID: 05-103-08107

Inspection: 679702692



Photo 1. Location looking north.




Photo 2. Gas leaking at well head.



Inspection Photos

Location Name: CONTINENTAL 2-17

Location ID: 05-103-08107

Inspection: 679702692



Photo 3. No well head sign.



Photo 4. No tank label.



Inspection Photos

Location Name: CONTINENTAL 2-17

Location ID: 05-103-08107

Inspection: 679702692



Photo 5. Sign missing nearest public road.

