

Inspection Photos

Location Name: CONTINENTAL 3-17

Location ID: 05-103-08106

Inspection: 679702694



Photo 1. Location looking east.



Photo 2. Tank without sign.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: CONTINENTAL 3-17

Location ID: 05-103-08106

Inspection: 679702694



Photo 3. Separator vent stack without bird protection.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources