

**Inspection Photos**  
**Location Name: GE29-07**  
**Location ID: 309301**



**Photo 1 SEP**

**Photo 2 WH/ sound walls for motor skid**

**Inspection Photos**  
**Location Name: GE29-07**  
**Location ID: 309301**



**Photo 3 Electric fence in disrepair**

**Photo 4 electric fence in disrepair**