
Main Pass
Schlumberger
Company: Halliburton Energy Services
Well: Hilcorp Alaska, LLC
Field: Milne Point
Location: Milne Point, Alaska
Run 1
Run 2
Run 3
Run 4
Run 5
Run 6
Run 7
Run 8
Run 9
Run 10
Run 11
Run 12
Run 13
Run 14
Run 15
Run 16
Run 17
Run 18
Run 19
Run 20
Run



Repeat Pass

Database File	02_feb\clough nr 311-3\tep_clough_nr_311-3_pn_9-12-18.db
Dataset Pathname	repeat:2
Presentation Format	rss_pdm_hunter
Dataset Creation	Wed Sep 12 18:45:29 2018
Charted by	Depth in Feet scaled 1:240

Sensor	Offset (ft)	Schematic	Description	Length (ft)	O.D. (in)	Weight (lb)
			Titan CHD-15875-GO 1 7/8in 11.11/16" Hyperchrome Electric Cable Head w/ 1" Fishing Neck	1.03	1.69	5.40
			HWS_TCU-002 (001704) HWS Telemetry Control Unit (TCU002)	2.30	1.69	10.87
TCUTEMP TCUVOLT GCL_CCL	14.69 14.69 13.97					
			HWS_GCL-001 (001475) HWS Gamma Ray Collar Locator (1.687")	2.69	1.69	13.40
GCL_GR GCL_GR	12.59 12.59					
Long Far Near Anci	6.25 6.25 6.25 6.25					
			HWS_RAS-RAS002 (003040) Hunter Well Science Pulsed Neutron Tool	11.75	1.69	55.92
			HWS_TBN-001 (001725) HWS Centering Bull Nose (1.687")	0.25	1.69	0.99

Dataset: tep_clough_nr_311-3_pn_9-12-18.dls fieldwellrun1main.2
Total length: 10.02 ft
Total weight: 86.48 lb
O.D.: 1.69 in

Calibration Report

Database File	c:\programdata\weatherford\data\02_feb\clough nr 311-3\tep_clough_nr_311-3_pn_9-12-18.db
Dataset Pathname	main.2
Dataset Creation	Wed Sep 12 18:51:11 2018

Gamma Ray Calibration Report

Serial Number:	001475	
Tool Model:	001	
Performed:	(Not Performed)	
Calibrator Value:	1.0	GAPI
Background Reading:	0.0	
Calibrator Reading:	1.0	
Sensitivity:	1.0000	GAPI/

Company	TEP Rocky Mountain LLC
Well	Clough NR 311-3
Field	Rulison
County	Garfield
State	Colorado