

Construction and Storm Water Inspection

January 18, 2019

Operator: CRESTONE PEAK RESOURCES OPERATING LLC – 10633

Location ID: 451044

Inspection Document #: 674902408

Weld County, CO

NWNE Section 19 T2N R68W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: CRESTONE PEAK RESOURCES OPERATING LLC – 10633/2N68W19

Location ID: 451044



Photo 1. Photo taken from the entrance of the location off CR 205, facing North. Operator has installed gravel potentially to limit tracking onto the county road. BMPs in proper functioning condition at the time of this inspection.



Photo 2. Photo taken from the entrance of the location off CR 205, facing South. See comments from Photo 1.

Inspection Photos

Location Name: CRESTONE PEAK RESOURCES OPERATING LLC – 10633/2N68W19

Location ID: 451044



Photo 3. Photo taken from the access road, facing South. Photo depicts road base along access road.



Photo 4. Photo taken from the access road looking into the location, facing West. See comments from Photo 3.

Inspection Photos

Location Name: CRESTONE PEAK RESOURCES OPERATING LLC – 10633/2N68W19

Location ID: 451044



Photo 5. Photo taken from the northern perimeter of the location, facing West. Photo illustrates the ditch and berm BMP that has been installed around the perimeter of the location.



Photo 6. Photo taken from the northern perimeter of the location, facing East. See comments from Photo 5.

Inspection Photos

Location Name: CRESTONE PEAK RESOURCES OPERATING LLC – 10633/2N68W19

Location ID: 451044



Photo 7. Photo taken from the northwestern perimeter of the location, facing South. The topsoil stockpile being stored along the eastern area has been temporarily stabilized with equipment tracking.



Photo 8. Photo taken from the northwestern perimeter of the location, facing East. See comments from Photo 1.

Inspection Photos

Location Name: CRESTONE PEAK RESOURCES OPERATING LLC – 10633/2N68W19

Location ID: 451044



Photo 9. Photo taken from the southwestern perimeter of the location, facing South. See comments from Photo 1.



Photo 10. Photo taken from the southwestern perimeter of the location, facing East. See comments from Photo 1.

Inspection Photos

Location Name: CRESTONE PEAK RESOURCES OPERATING LLC – 10633/2N68W19

Location ID: 451044



Photo 11. Photo taken from the southern perimeter of the location, facing East. See comments from Photo 1.



Photo 12. Photo taken from the southern perimeter of the location, facing West. See comments from Photo 1.