

Inspection Photo (s)
Valley Farms E 11
API # 05-045-13221
Inspection # 689303028



Location Photo #1



Location Photo #2

Inspection Photo (s)
Valley Farms E 11
API # 05-045-13221
Inspection # 689303028



Location Photo #3, Condensate in drip pan.



Location Photo #4, Holes in secondary containment liner.

Inspection Photo (s)
Valley Farms E 11
API # 05-045-13221
Inspection # 689303028



Location Photo #5, Holes in secondary containment liner.



Location Photo #6, Holes in secondary containment liner.