

Inspection Photo (s)
Valley Farms D 1
API # 05-045-12083
Inspection # 689303030



Location Photo #1



Location Photo #2

Inspection Photo (s)
Valley Farms D 1
API # 05-045-12083
Inspection # 689303030



Location Photo #3, Stained ground in battery containment near load out point.



Location Photo #4, , Stained ground in battery containment near load out point.

Inspection Photo (s)
Valley Farms D 1
API # 05-045-12083
Inspection # 689303030



**Location Photo #5, Unlabeled, unmarked,
open bucket with unknown contents.**



**Location Photo #6, Condensate on ground
near separator.**

Inspection Photo (s)
Valley Farms D 1
API # 05-045-12083
Inspection # 689303030



Location Photo #7, Holes in containment secondary liner.



Location Photo #8, Holes in containment secondary liner.

Inspection Photo (s)
Valley Farms D 1
API # 05-045-12083
Inspection # 689303030



Location Photo #9, Holes in containment secondary liner.



Location Photo #10, Holes in containment secondary liner.