

Inspection Photo (s)
Valley Farms C 7
API # 05-045-12203
Inspection # 689303032



Location Photo #1



Location Photo #2



Inspection Photo (s)
Valley Farms C 7
API # 05-045-12203
Inspection # 689303032



Location Photo #3



**Location Photo #4, Hole in secondary
containment liner.**

Inspection Photo (s)
Valley Farms C 7
API # 05-045-12203
Inspection # 689303032



Location Photo #5, Mechanical condition of tank and frost free valve.