

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/23/2019

Submitted Date:

01/23/2019

Document Number:

692601223**FIELD INSPECTION FORM**
 Loc ID 416396 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10489Name of Operator: AUGUSTUS ENERGY RESOURCES LLCAddress: 2016 GRAND AVENUE #ACity: BILLINGS State: MT Zip: 59102**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**12 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Jones, Greg	(970) 630-3909	greg.jones@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
416409	WELL	PR	07/12/2010	GW	125-11813	S G Hagemann 34-13 1S45W	PR

**General Comment:**Routine Inspection

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Two track through pasture		
Corrective Action		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Lease signs mounted to fence at meter shed		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign mounted to fence at unit		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	OTHER		
Comment:	Metal panels around meter shed and VGS		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Metal panels around unit and wellhead		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Vertical Separator	# 3		
Comment:	3-Vertical gas separators 50% buried by meter shed		
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:	Shared meter run for SG Hagemann 34-13, 33-13, 44-13 on east side of location		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	

Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Electric panel and telemetry equipment		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Jensen unit		
Corrective Action:			Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	416409	Type:	WELL	API Number:	125-11813	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production. Central meter run for (SG Hagemann 33-13, 34-13, 44-13)								
Corrective Action:							Date:		

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT